



C4 Violates PickIt Rules
Consider Removing

During Programming JMP_A4 should be installed
other jumpers not required. There should be
no pull-up on PGC/PGD during programming

PIC12F675 Learning Board from EBAY
Schematic drawn by Aardvark Labs